

Class 1 Government Contract

1. Document Numbers

D20/87485 - RFQ 2048

2. Name and Address of the contractor

Name: Moduplay Group Pty Ltd

Address: 17-19 Waverley Drive Unanderra, NSW 2526

3. Particulars of any related body corporate (within the meaning of the Corporations Act 2001 of the Commonwealth) in respect of the contractor, or any other private sector entity in which the contractor has an interest, that will be involved in carrying out any of the contractor's obligations under the contract or will receive a benefit under the contract

N/A

4. The date on which the contract became effective and the duration of the contract

14/09/2020 13 Months

5. Particulars of the project to be undertaken, the goods or services to be provided or the real property to be leased or transferred under the contract

Bondi Park Outdoor Fitness Station.

Council plans to upgrade and improve the existing outdoor fitness station located at Bondi beach. The works will consist of new softfall, relocation of drinking fountain and the repair of fitness equipment.

6. The estimated amount payable to the contractor under the contract

\$152,599.53 inc. GST

7. A description of any provisions under which the amount payable to the contractor may be varied

N/A

8. A description of any provisions with respect to the renegotiation of the contract

N/A

9. In the case of a contract arising from a tendering process, the method of tendering and a summary of the criteria against which the various tenders were assessed

An RFQ was carried out via Tenderlink with the following criteria-

Technical:

- Proposed program & method.
- Proposed personnel including sub contractors.
- Previous experience with similar projects.
- Work Health and Safety.
- Environmental management system.
- Quality management system
- Satisfaction of financial integrity and insurance.

Non Technical:

• Lump sum price.

10. A description of any provisions under which it is agreed that the contractor is to receive payment for providing operational or maintenance services

Maintenance on turf for a period of 13 weeks.