

RESPONSE REPORT BRONTE

Waverley Council Response Report presented to 17 February 2020 Bronte Precinct meeting

Date	Motion	Response
<p>18 November 2019</p>	<p>Mirimar Ave Footpath</p> <p>Background: Most of the eastern footpath in Mirimar Avenue was replaced in July 2019. The sections that were not replaced were (1) outside no. 9, owing to ongoing construction at the site for which the owner is responsible, and (2) at the south-eastern end on the corner of Hewlett Street. The reason for not replacing the latter is unknown, but may be because the existing footpath was not broken or cracked. However, this section is over 60 years old, the cement has worn down leaving the blue metal raised above the level of the cement, the blue metal is smooth and slippery, and the footpath is on a steep incline. The footpath is therefore dangerous as it very slippery.</p> <p>Motion: Bronte Precinct request from Council, That the sections of the footpath at the south-east end of Mirimar Avenue at the corner of Hewlett Street that were not replaced in July 2019 should be replaced as they are worn and present a slip hazard. Moved: Michael Donnan Seconded: Grant Beard</p>	<p>Motion has been forwarded to the Executive Manager Creating Waverley who is investigating the matter. A full response will be sent to the Precinct.</p>

February 2020