

BONDI PAVILION RESTORATION AND CONSERVATION PROJECT



Bondi Pavilion – Upcoming Works

Upcoming Works

- North Pavilion Colonnade Waterproofing
- Main Pavilion Removal of Scaffolding
- Main Pavilion Fitout (Continue)
- Theatre Fitout (Continue)
- Remedial Restoration of Heritage Facade (Continue)
- North Amenities & Pottery Fitout (Continue)
- Concrete Slabs Poured To Courtyard
- Queen Elizabeth Drive Works (Continue)
- Western Landscape Commence Stage 3B/3C

Progress Photos

Pavilion Terracotta Roof Tiles



Progress Photo

South Colonnade Slab Poured



Progress Photos

North Amenities Early Stage Fitout




Progress Photos

Theatre Fitout



Progress Photos

Heritage Preservation



Progress Photos

Gatehouse Fitout



Progress Photos

Queen Elizabeth Drive Works



Bondi Pavilion – Completed Works

Completed Works

- Pavilion Terracotta Roof Tiles
- Main Pavilion Lift Commissioned
- Main Pavilion Service Installation
- North Pavilion Grease Arrestor installed
- Gatehouse Ceilings Installed
- Service Trenching to Tenancy Shells
- South Colonnade Slab Poured
- North Pavilion Waste Room ,Pottery Room, Amenities Slab Poured
- North Colonnade Slab Poured
- North Loggia Slab Poured
- Tenancy Shell 1 Deck Poured